2022 Lake Parker Water Quality Monitoring Results: Lay Monitoring Program and LaRosa Partnership Program

Mark Mitchell, Lake Monitoring and Community Outreach Coordinator
VT Department of Environmental Conservation, UVM Lake Champlain Sea Grant










Lay Monitoring Program (LMP) Lake Sampling Overview

- Weekly from Memorial Day to Labor Day (minimum of 8 samples for summer mean):
 - Basic Sampling: Measure Secchi disk transparency depth (clarity)
 - Supplemental Sampling: Collect water samples with hose at twice Secchi depth that are lab tested for total phosphorus (nutrient) concentration and chlorophyll-a (algae) concentration
 - Complete a lake sampling webform (and report cyanobacteria conditions)



https://dec.vermont.gov/watershed/lakes-ponds/monitor/lay-monitoring




Vermont Lake Score Card Lake Parker


https://dec.vermont.gov/watershed/lakes-ponds/data-maps/scorecard


Scores


Water Quality Data


Lake Information
















(Image courtesy of Kasco Marine)

https://kascomarine.com/blog/pond-lake-zone-identification/

Internal Phosphorus Loading From Anoxic Sediment





Sampling	Hose Sample	Hose Total Phosphorus	Hose Chlorophyll-a	Secchi Depth Without View	Secchi Depth With View
Date	Depth (m)	(ug/l)	(ug/l)	Tube (m)	Tube (m)
5/23/2022	4	23.2	6.2		2
6/1/2022	6	13.7	5.46	3	
6/11/2022	7	16.7	4.44	3.5	
6/20/2022	5	15.5	4.88		2.5
6/26/2022	7	17.2	9.24		3.5
7/3/2022	7	15.4	8.48		3.5
7/13/2022	6.8	16.2	6.01		3.4
7/20/2022	8	19.4	9.92		4
7/27/2022	8	17.7	13.6	4	4
8/3/2022	8	18.3	4.01	4	4
8/8/2022	8.4	16.9	5.7		4.2
8/15/2022	10	23.6	17.9	5	5
8/21/2022	10	23.8	4.47	4.5	5
8/31/2022	9	17.2	12.5	4.5	4.5
Mean		18.2	8.06	4.07	3.8
VT Class B2	Photosynthetic	18	7	2.6	2.6
Standards	(Euphotic) Zone				


LAKE PARKER

Annual Data (Station 1)

Annual Data (Station 1)

	Days Sampled		Secchi View Tube	а	Summer TP	Spring TP		Days Sampled			Chloro- a	Summer TP	Spring TP
Year		(m)	(m)	(µg/I)	(µg/l)	(µg/l)	Year		(m)	(m)	(µg/l)	(µg/l)	(µg/l)
1979	23	3.2		6.2			2001	11	4.3		4.8	16.6	12.3
1980	13	3.7		7.2		17.0	2002	10	3.4		5.4	25.7	17.0
1981	13	3.2		5.9		22.0	2003	12	4.0		16.2	22.0	
1982	13	4.0		5.2		18.0	2004	13	3.3		7.1	16.6	14.3
1983	13	4.2		5.6	14.1	14.0	2005	11	3.7		8.0	17.7	15.1
1984	13	3.6		5.8	14.9	13.0	2006	12	2.8		8.7	22.3	17.3
1985	12	5.3		6.9	15.2	14.0	2007	12	3.5		6.6	17.0	22.5
1986	12	4.5		6.1	13.8	13.0	2008	14	2.2		16.6	25.3	
1987	12	4.0		5.4	16.0	12.0	2009	15	2.4		6.5	17.4	18.6
1988	12	2.4		8.0	17.2		2010	14	3.1		8.1	21.6	
1989	12	3.8		18.7	22.8		2011	14	2.5		8.4	19.2	
1990	12	2.5		14.4	20.0	19.0	2012	12	2.9		4.8	15.4	
1991	12	4.2		5.9	14.8	15.0	2013	9	2.4		14.7	19.7	
1992	13	3.6					2014	12	2.9		5.7	17.5	
1993	12	4.0		4.8	13.0		2015	15	2.2		7.0	16.1	
1994	10	2.7		7.6	15.9		2016	14	4.1		7.5	17.7	
1995	11	4.1		8.1	15.1	21.0	2017	12	3.1		8.4	18.7	
1996	9	3.5					2018	13	4.0		5.7	15.5	
1997	9	2.8		5.7	19.6	14.0	2019	15	3.3		8.6	16.1	17.0
1998	9	3.4		6.5	20.7		2021	13	4.2		4.7	15.6	
1999	11	4.3		8.5	15.0	16.7	VT Star	dard*	2.6		7.0	18.0	
2000	12	3.5		6.5	17.1	19.3					es.		
VT Stand	ard*	2.6		7.0	18.0								

^{*} VT Water Quality Standards Nutrient Criteria for Class B2 Lakes > 20 acres.



LaRosa Partnership Program (LPP) Tributary Sampling Overview

- Tributaries first sampled in 2022 ~biweekly
 (8X) from April through July + ~2 storm events
- 523558-Tetrualt Rd culvert
 - Effects from upstream farms
 - Overall concern with nutrient levels in lake
 - Large sediment deposits at mouth of brook
- 523559-Walking path bridge#1
 - Effects from upstream farm
 - Overall concern with nutrient levels in lake
- 523560-Parker road 1149
 - Overall concern with nutrient levels in lake


LPP Sample Parameters Overview


Total Phosphorus

- Impacts
 - Feeds plants, algae and cyanobacteria
 - Aquatic Biota, Aesthetics, Recreation Uses
- Human Sources
 - Runoff from roads, lawns, agriculture, logging
 - Malfunctioning septic systems
- Vermont Water Quality Standards Nutrient Criteria for Aquatic Biota Use (+ Biological Criteria)
 - Not to be exceeded at low median monthly flow (baseflow) during June through October
 - 12 ug/L for small high gradient streams (SHG)
 - 15 ug/L for medium high gradient streams (MHG)
 - 27 ug/L for warm-water medium gradient streams and rivers (WWMG)


Total Nitrogen


- Impacts
 - Feeds plants, algae and cyanobacteria
 - Aquatic Biota, Aesthetics, Recreation Uses
- Human Sources
 - Runoff from roads, lawns, agriculture, logging
 - Malfunctioning septic systems
- Vermont Water Quality Standards
 - Not to exceed 5.0 mg/l as NO3-N at flows exceeding low median monthly flows, in Class B(1) and B(2) waters.
 - Not to exceed 2.0 mg/l as NO3-N at flows exceeding low median monthly flows, in Class A(1) and A(2) waters at or below 2,500 feet elev.






High-Resolution Land Cover Summary









2022 Lake Parker Tributary Total Phosphorus Monitoring Results



Tributary	Minimum TP (ug/l)	Average TP (ug/I)	2022 Max TP (ug/l)
Parker road 1149	8.2	11.3	14.6
Tetrualt Rd culvert	9.2	17.3	36.6
Walking path bridge#1	16.6	23.8	42.1




2022 Lake Parker Total Nitrogen Monitoring Results



Tributary Site	Minimum TN (ug/L)	Average TN (ug/L)	Maximum TN (ug/L)
Parker road 1149	0.22	0.3	0.47
Tetrualt Rd culvert	0.25	0.34	0.42
Walking path bridge#1	0.24	0.36	0.54

USGS Streamflow – Barton River, Coventry



2022 Monitoring Summary & 2023 Next Steps



- Lay Monitoring Program (LMP)
 - 2022 Summary: Deep hose samples have higher total phosphorus concentrations than surface samples due to internal loading from anoxic sediment
 - 2023 Next Steps: LMP volunteer collects biweekly surface and near-bottom (1 m) samples while LMP coordinator collects water quality vertical profile during visit; add caffeine testing as human wastewater indicator (i.e. septic systems)
- LaRosa Partnership Program (LPP)
 - 2022 Summary: Highest TP/TN from Walking path bridge#1 & Tetrualt Rd culvert
 - 2023 Next Steps: LPP volunteers continue collecting biweekly samples through August at all sites with a focus on Walking path bridge#1 & Tetrualt Rd culvert; add NE tributary site (see maps in slides below)

